

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 24 March 2020 Australia – Victoria

No. 115(T) - 2020

Local Port of Port Phillip

Sandringham

Sandringham Harbour - Temporary Starboard Lateral Buoy Light Non-Operational

Date: Immediate

Previous Notice: 248(T) - 2019 is referred.

Details: Mariners are advised that the temporary Starboard Lateral Buoy light with

characteristics FI(2)G.5s, situated 30m from the end of Sandringham Breakwater at approximate location 37°56.507′S, 144°59.532′E (WGS84) is non-operational.

Mariners are advised to navigate with caution within the vicinity of Sandringham

Harbour.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

