

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 27 October 2021**

**Australia – Victoria**

**No. 314(T) - 2021**

**Local Port of Port Phillip**

**Point Wilson**

**Point Wilson Pier Works Exclusion Zone – Lit Special Mark Buoys Missing**

**Date: Immediate**

**Previous Notice: 239-2020 is referred**

**Details:** Mariners are advised that 3 lit special mark buoys associated with the Point Wilson Pier works exclusion zone are missing, as outlined in the table below.

Buoy type	Approximate Location (WGS84)	Light Characteristics
Yellow SLB1250 Special Mark	38°05.198'S, 144°30.926'E	Iso2s
Yellow SLB1250 Special Mark	38°05.382'S, 144°31.471'E	Iso2s
Yellow SLB1250 Special Mark	38°05.636'S, 144°32.479'E	Iso2s

The buoys and lights will be re-instated as soon as practicable.

**Mariners are advised to navigate with caution when within the vicinity of Point Wilson.**

**Charts & Publications**

**Affected:** AUS 157, 143.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please Parks Victoria on 13 1963.**

Deven Sumpth

A/ Senior Manager Local Ports and Waterways  
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).