

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

09 July 2026
Victoria - Australia

No. 345(T) - 2025

Local Port of Western Port

Eastern Entrance
Starboard lateral Buoy – Damaged and Unlit

Date: Immediate

Details: Mariners are advised that the Starboard lateral buoy marking the Eastern Entrance to Western Port, with characteristics Fl(1)G 3s at approximate location: 38°32.433'S 145°21.067'E (WGS84), has been damaged and is unlit.

The light will be re-established as soon as practical.
The damaged buoy remains in situ.

Mariners are advised that further hazards to navigation may become present and to navigate with caution within the vicinity of Eastern Entrance.

Charts & Publications

Affected: AUS801, AU439145

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Moorings and Port Services Manager
Maritime and Waterways Directorate

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.