

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

14 October 2026
Australia – Victoria

No. 475(T) - 2026

Local Port of Port Phillip

Williamstown
Williamstown Mooring Field - Lit Isolated Danger Buoy - Missing

Date: **Immediate**

Details: Mariners are advised that the Isolated Danger Buoy, lit with characteristics FI(2)10s, situated in the eastern portion of the Williamstown Mooring Field at approximate location 37°51.413'S, 144°54.229'E (WGS84) is missing.

The buoy and light will be reinstated as soon as practicable.

Charts & Publications

Affected: AUS143, AUS155, AU5MEL01, AU438144.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Moorings and Port Service Operations Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.