Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

04 November 2026
Victoria - Australia

No. 500(T) - 2026

Local Port of Port Phillip

Hampton
Hampton Shared Wind Sports Zone - Special Mark Buoy Missing

Date: **Immediate**

Details: Mariners are advised that the unlit Special Mark Buoy, marking the northern extent of the Hampton shared wind sports zone, at approximate location: 37°56.057'S, 144°59.481'E (WGS84), is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the Hampton shared wind sports zone

Charts & Publications Affected: AUS143, AU438145.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Moorings and Port Service Operations Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.