

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 28 January 2021
Australia – Victoria

No. 026(T) - 2021

Local Port of Port Phillip

Indented Head
Governor Reef Channel – Starboard Lateral Mark Buoy Missing

Date: **Immediate**

Details: Mariners are advised that the lit starboard lateral mark buoy, with characteristics fl.G.3s, marking Governor Reef Channel at approximate location 38°09.249'S, 144°43.553'E (WGS84) is missing.

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Governor Reef.

Charts & Publications

Affected: AUS 143 &157.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.