

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 31 August 2020 Australia – Victoria

No. 241 - 2020

Local Port of Port Phillip

Indented Head

Governor Reef Channel - Port Lateral Buoy Light Reinstated

Date: Immediate

Previous Notice: 234(T) – 2020 is referred and cancelled

Details: Mariners are advised that the Governor Reef Channel Port Lateral Buoy Light with

characteristics Fl.R.3s at approximate location 38°08.930'S, 144°43.336'E (WGS84)

has been reinstated.

Mariners are advised to exercise caution when navigating within the

vicinity of Governor Reef.

Charts & Publications

Affected: AUS 143, 157.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Graeme Davis

District Manager Port Phillip Western Port Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

