

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 11 June 2021
Australia – Victoria

No. 173(T) - 2021

Local Port of Port Phillip

Indented Head
Governor Reef Channel – Lit Starboard Lateral Buoy Missing

Date: **Immediate**

Details: Mariners are advised that the Starboard Lateral Buoy marking Governor Reef Channel, lit with characteristics Fl.G.3s at approximate location (WGS84): 38°08.925'S, 144°43.379'E, is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Governor Reef.

Charts & Publications

Affected: AUS 143 & 157.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.