

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 18 November 2020**  
**Australia – Victoria**

**No. 321(T) - 2020**

**Local Port of Port Phillip**

**Hampton**  
**Hampton Shared Wind Sports Zone - Buoy Missing.**

**Date:** **Immediate.**

**Details:** Mariners are advised that the unlit special mark buoy marking the northern extent of the Hampton shared wind sports zone, at approximate location 37°56.057'S, 144°59.481'E (WGS84) is missing.

The buoy will be reinstated as soon as practicable.

**Mariners are advised to navigate with caution within the vicinity of Hampton shared wind sports zone.**

## **Charts & Publications**

**Affected:** AUS 143, 155

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Graeme Davis

District Manager Port Phillip Western port  
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).