

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 11 January 2022
Australia – Victoria

No. 013(T) - 2022

Local Port of Port Phillip

Indented Head

Wave Monitoring Station Lit Special Mark Buoy Missing

Date: Immediate

Previous Notice: 419(T)-21 is referred

Details: Mariners are advised that the lit special mark buoy with characteristics Fl.(Y).2.5s, marking a wave monitoring station installed in the vicinity of Indented Head at approximate location 38°08.156'S, 144°45.184'E (WGS84), is currently missing.

The wave monitoring station currently has a red buoy attached and has its own light, but it may be more difficult to see.

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution when within the vicinity of the wave monitoring buoys.

Charts & Publications

Affected: AUS 143, 157

Further Notice: A further Notice will be issued.

If you require any further information, please contact Deakin University on 0409 502 980.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.