

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 06 February 2023 Australia – Victoria

No. 067(T) - 2023

Local Port of Port Phillip

Seaford

Wind Sports Zone Southern Special Mark Buoy Missing

Date: Immediate

Details: Mariners are advised that the unlit Special Mark Buoy, marking the southern

extent of the Shared Wind Sports Zone, at approximate location (WGS84)

38°19. 865'S, 144°57.765'E, is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the

Shared Wind Sports Zone.

Charts & Publications

Affected: AUS 143, 150

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Peter Kemp

A/Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

