

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 10 March 2020**  
**Australia – Victoria**

**No. 100(T) - 2020**

**Local Port of Port Phillip**

**Sorrento**

**Sorrento Channel - Starboard Lateral Mark Lead Light Navigation Pile - Missing**

**Date:** Immediate

**Details:** Mariners are advised that the Sorrento Channel Starboard Lead Light Pile, lit with characteristics FL. G 5s, at approximate location (WGS84) 38° 19.479'S, 144° 44.534'E is missing.

A temporary starboard lateral buoy has been installed at the same location.

The pile and navigation light will be reinstated as soon as practicable.

**Mariners are advised to navigate with caution within the vicinity of the missing pile.**

**Charts & Publications**

**Affected:** AUS 143,158.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963**

Victor Teoh  
Senior Manager Local Ports and Waterways  
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).