

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 11 June 2021 Australia – Victoria

No. 172(T) - 2021

Local Port of Port Phillip

Elwood

Special Mark Racing Buoy R3 Out of Position

Date: Immediate

Previous Notice: 089 (T) – 21 is referred

Details: Mariners are advised that the R3 lit yellow special mark buoy, with characteristics

fl.Y.4s, with charted position off Elwood at approximate location

37°53.168'S, 144°56.386'E (WGS84), is out of position.

The buoy is currently located in the vicinity of Lagoon Pier to the north of its charted position, at approximate location 37°50.883'S, 144°56.417'E (WGS84).

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the buoy.

Charts & Publications

Affected: AUS 143, 155.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

