

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**Melbourne, 18 June 2021**

**Australia – Victoria**

**No. 192 - 2021**

**Local Port of Port Phillip**

**Indented Head**

**Governor Reef Channel – Lit Starboard Lateral Buoy Reinstated**

**Date:** Immediate

**Previous Notice:** 173(T) – 2021 is referred and cancelled

**Details:** Mariners are advised that the Starboard Lateral Buoy marking Governor Reef Channel, lit with characteristics Fl.G.3s at approximate location (WGS84): 38°08.925'S, 144°43.379'E, has been reinstated.

**Mariners are advised to navigate with caution within the vicinity of Governor Reef.**

**Charts & Publications**

**Affected:** AUS 143 &157.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Victor Teoh

Senior Manager Local Ports and Waterways  
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).