

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

23 April 2025 Victoria - Australia

No. 208(T) - 2025

Local Port of Port Phillip

Portsea

Portsea Hole - Port Phillip Heads Marine National Park special mark buoys - Unlit

Date: Immediate

Details: Mariners are advised that the special mark buoys, with characteristics Fl.Y.5s

marking the boundary of Portsea Hole (Port Phillip Heads Marine National

Park), at approximate locations (WGS84) are unlit.

• 38° 18.567'S, 144° 42.667'E (North)

• 38° 18.717'S, 144° 42.850'E (Eastern)

38° 18.800'S, 144° 42.750'E (Southern)

• 38° 18.667'S, 144° 42.533'E (Western)

The lights will be reinstated as soon as practical.

Mariners are advised to continue to navigate with caution and within the

speed limit near the Marine National Park.

Charts & Publications

Affected: AUS 144, AUS 143, AU5RIP01

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.

