

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 06 September 2021 Australia – Victoria

No. 269 - 2021

**Local Port of Port Phillip** 

**Portsea** 

Port Phillip Heads Marine National Park - Portsea Hole Eastern Buoy Reinstated

Date: Immediate

**Previous Notice:** 245(T)-21 is referred and cancelled

**Details:** Mariners are advised that the lit special mark buoy, with characteristics

Fl.Y.5s, marking the eastern boundary of Portsea Hole at approximate location: 38°18.714′S, 144°42. 863′E (WGS84), has been reinstated.

Mariners are advised to navigate with caution and within the speed limit

within the vicinity of Portsea Hole.

**Charts & Publications** 

Affected: AUS 144, 158

**Further Notice:** No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

A/ Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <a href="mailto:noticetomariners@parks.vic.gov.au">noticetomariners@parks.vic.gov.au</a>. To view Notices, visit <a href="https://www.parks.vic.gov.au">www.parks.vic.gov.au</a>.

