

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 05 October 2020 Australia – Victoria

No. 280(T) - 2020

**Local Port of Port Phillip** 

**Brighton** 

Royal Brighton Yacht Club - Buoy #5 Light Non-Operational.

Date: Immediate.

**Details:** Mariners are advised that the Royal Brighton Yacht Club Buoy #5 with

characteristics FI(4).Y.12s situated north of Middle Brighton Harbour, at approximate location 37°53.811'S, 144°58.459'E (WGS84) is not operational.

The light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the

buoy.

**Charts & Publications** 

**Affected:** AUS 143, 155

**Further Notice:** A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <a href="mailto:noticetomariners@parks.vic.gov.au">noticetomariners@parks.vic.gov.au</a>. To view Notices, visit <a href="mailto:www.parks.vic.gov.au">www.parks.vic.gov.au</a>.

