

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**02 June 2026**  
**Victoria - Australia**

**No. 284(T) - 2026**

**Local Port of Port Phillip**

**Indented Head**  
**Governor Reef Channel – Lit Starboard Lateral Buoy – “Missing”.**

**Date:** **Immediate**

**Details:** Mariners are advised that the Governor Reef Lit Starboard Lateral Buoy with light sequence Fl(1)G 3s at approximate location: 38°09.232'S, 144°43.552'E (WGS84) is missing.

The buoy will be reinstated as soon as practicable

**Mariners are advised to exercise caution when navigating within the vicinity of Governor Reef.**

**Charts & Publications**

**Affected:** AUS143, AUS157, AU439144.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Chris Anderson  
Moorings and Port Service Operations Manager  
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).