

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 19 November 2019
Australia – Victoria

No. 285(T) – 2019

Local Port of Port Phillip

Sandringham
Sandringham Harbour - Temporary Starboard Lateral Buoy - Reinstated

Date: **Immediate**

Previous Notice: 248(T) – 2019 is referred. 256(T) – 2019 is referred and cancelled.

Details: Mariners are advised that the temporary Starboard Lateral Buoy lit with characteristics Fl(2)G.5s 30m from the end of Sandringham Breakwater at approximate location 37°56.507'S, 144°59.532E (WGS84) has been reinstated.

Mariners are advised to navigate with caution within the vicinity of Sandringham Harbour.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Deven Sumpth

A/ Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.