

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

1 August 2024
Australia – Victoria

No. 318(T) - 2024

Local Port of Port Phillip

Port Phillip Bay
Wave Monitoring Buoys Re-Established

Date: **Immediate**

Details: Mariners are advised that the following table of temporary wave monitoring buoys established in the below existing positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until approximately **January 2025**.

<i>Approximate Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Characteristics</i>
<u>Port Melbourne Waters</u>			
Werribee	37° 59.100' S	144° 46.512' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s
Central	38° 03.811' S	144° 52.012' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s
<u>Local Port of Port Phillip</u>			
Sandringham	37° 58.719' S	144° 59.730' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	SBL600 buoy - FL (Y) 2.5s Orange float - Unlit Wave buoy - FL (Y) 2.5s

Mariners are advised to navigate with caution within the vicinity of the wave monitoring buoys.

Charts & Publications

Affected: AUS143, AUS155, AUS157, AU5MEL01, AU5RIP01

Further Notice: A further Notice will be issued.

If you require any further information, please contact Deakin University on 5563 3224.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.




SLB600 BUOY



ORANGE FLOAT



WAVE MONITORING BUOY



BOUY ARRANGEMENT