

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

22 June 2026
Victoria - Australia

No. 321(T) - 2026

Local Port of Port Phillip

Portsea
Port Phillip Heads Marine National Park - Portsea Hole – Southern Buoy Unlit

Date: Immediate

Details: Mariners are advised that the lit special mark buoy with characteristics Fl.Y.5s, marking the Southern boundary of Portsea Hole (Port Phillip Heads Marine National Park), at approximate location: 38° 18. 817'S, 144° 42. 750'E (WGS84) is unlit.

The light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Portsea Hole.

Charts & Publications

Affected: AUS143, AUS144, AU5RIP01

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Mooring and Port Service Operations Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.