



# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**20 June 2025**  
**Australia – Victoria**

**No. 330(T) - 2025**

**Local Port of Port Phillip**

**Portsea**  
**Portsea Hole Western Boundary Lit Special Mark Buoy Missing**

**Date:** **Immediate**

**Details:** Mariners are advised that the lit special mark buoy with characteristics Fl.Y.5s, marking the western extent of Portsea Hole (Port Phillip Heads Marine National Park) at approximate location: 38°18.671'S, 144° 42.524'E (WGS84), is missing.

The Buoy has not yet been located and may be sighted off station. The buoy and light will be reinstated as soon as practicable.

**Mariners are advised to continue to navigate with caution and within the speed limit near the Marine National Park.**

## **Charts & Publications**

**Affected:** AUS143, AUS144, AU5RIP01, AU439144

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

David Ritman  
Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au) or visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au) to view Notices.