

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 08 November 2021

Australia – Victoria

No. 337(T) - 2021

Local Port of Port Phillip

Beaumaris

Damage to Ricketts Point Navigation Piles

Date: Immediate

Details: Mariners are advised of damage to several starboard and south cardinal marker piles on the boundary of Ricketts point Marine Sanctuary.

The damaged piles are in the following locations:

Description	Locations	Damage
starboard mark - northern-most pile	37° 59'14"S, 145° 01'02"E	Bent top mark
starboard mark - southern-most pile	37° 59'52"S, 145° 01'46"E	Missing day shape and 5 knot sign damaged
south cardinal mark - south-west corner pile	37° 59'57"S, 145° 02'03"E	Missing 2 lower triangles on the day shape
South cardinal mark – south east corner (Table Rock) pile	37° 59'52"S, 145° 02'18"E	Top mark bent and missing 1 lower triangle

The piles will be repaired as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Ricketts Point Marine Sanctuary.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further notice will be issued

If you require any further information, please contact Parks Victoria on 13 1963.

Deven Sumpth
A/Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.