

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

06 July 2026
Victoria - Australia

No. 340(T) - 2026

Local Port of Port Phillip

Rosebud
Rosebud - Wind Sports Special Mark Buoy - Missing

Date: **Immediate**

Details: Mariners are advised that the unlit Rosebud Wind Sports Special Mark Buoy, at approximate location: 38°21.217'S, 144°53.317'E (WGS84), is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the Shared Wind Sports Zone.

Charts & Publications

Affected: AUS 143

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Moorings and Port Service Operations Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.