

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

06 September 2024

Australia – Victoria

No. 368(T) - 2024

Local Port of Port Phillip

Sandringham Harbour

Starboard Lateral Buoy Unlit

Date: Immediate

Details: Mariners are advised that the temporary starboard lateral buoy with characteristics Fl(2)G.5s, situated 30-metres from the end of Sandringham Harbour Breakwater in approximate position 37°56.507'S, 144°59.532'E (WGS84) is unlit.

Mariners are advised to exercise caution when navigating in the vicinity of Sandringham Harbour.

Charts & Publications

Affected: AUS143, AUS155, AU5SAN01, AU438144.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman
A/ Manager Regional Operations
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.