

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

7 September 2026
Australia – Victoria

No. 412 - 2026

Local Port of Port Phillip

Rosebud
Additional Wave Monitoring Buoy removed and permanently discontinued

Date: **Immediate**

Previous Notice: **333(T)-25 is referred**

Details: Mariners are advised that the additional temporary wave monitoring buoy and Special Mark Buoy with Characteristics Fl(Y)2.5s that was added to the existing Rosebud site as listed in NTM 333(T)-25, at approximate location (WGS84): 38° 18.087' S, 144° 52.364' E has been removed and permanently discontinued.

This additional buoy has been withdrawn. One wave monitoring buoy remains at this location.

Charts & Publications

Affected: AUS143, AU5RIP01, AU439144

Further Notice: No further Notice will be issued.

If you require any further information, please contact DEECA on 136 186.

Chris Anderson
Moorings and Port Service Operations Manager
Maritime and Waterways Operations One wave monitoring buoy remains at this location

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.




SLB600 BUOY



ORANGE FLOAT



WAVE MONITORING BUOY



BOUY ARRANGEMENT