

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

28 September 2026

Victoria - Australia

No. 442(T) - 2026

Local Port of Port Phillip

Indented Head

Governor Reef Channel – Lit Starboard Lateral Buoy (North) – “Missing”.

Date: Immediate

Previous Notices: NTM 284(T)-2026 is referred.

Details: Mariners are advised that the Lit Starboard Lateral Buoy (North) at Governor Reef with light sequence Fl(1)G 3s at approximate location: 38°08.925'S, 144°43.379'E (WGS84) is missing.

The buoy will be reinstated as soon as practicable

Mariners are advised to exercise caution when navigating within the vicinity of Governor Reef.

Charts & Publications

Affected: AUS143, AUS157, AU439144.

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Chris Anderson
Mooring and Port Service Operations Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.