

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**04 September 2025**  
**Australia – Victoria**

**No. 450 – 2025**

**Local Port of Port Phillip**

**Sandringham**  
**Sandringham Harbour Temporary Starboard Lateral Buoy Permanently Discontinued**

**Date:** **Immediate**

**Previous Notice:** 248(T)-19 is referred and cancelled,  
451-25 is referred.

**Details:** Mariners are advised that the temporary Starboard Lateral Buoy, marking the breakwater at Sandringham Harbour, with characteristics Fl(2)G 5s, at approximate location (WGS84): 37°56.507'S, 144°59.532'E, is no longer required.

The temporary buoy has been removed and is permanently discontinued.

**Mariners are advised to navigate with caution in the vicinity of the of Sandringham Harbour.**

**Charts & Publications**

**Affected:** AUS143, AUS155, AU5SAN01, AU438144.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

David Ritman  
Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au)