

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

04 September 2025
Australia – Victoria

No. 451 – 2025

Local Port of Port Phillip

Sandringham

Sandringham Harbour Starboard Lateral Mark Beacon Moved

Date: Immediate

Previous Notices: 121(T)-19 is referred and cancelled,
235(T)-25 is referred,
450-25 is referred.

Details: Mariners are advised that the Sandringham Harbour Starboard Lateral Mark Beacon, with characteristics Fl(2)G 5s, has been replaced and moved approximately 0.02NM west (~40 metres) and is now situated at approximate location 37°56.484'S, 144°59.530'E (WGS84).

The old Sandringham Harbour Starboard Lateral Mark Beacon pile remains temporarily in situ and is lit with an orange flashing light and unmarked. The old pile will be removed as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Sandringham Harbour.

Charts & Publications

Affected: AUS143, AUS155, AU5SAN01, AU438144.

Further Notice: No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman
Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.