

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**25 October 2024**  
**Australia – Victoria**

**No. 454 - 2024**

**Local Port of Port Phillip**

**Sandringham Harbour**  
**Sandringham – Starboard Lateral Buoy – Light Re-established**

**Date:** **Immediate**

**Previous Notice:** **368(T)-2024 is referred and cancelled**

**Details:** Mariners are advised that the temporary starboard lateral buoy light with characteristics Fl(2)G.5s, situated 30-metres from the end of Sandringham Harbour Breakwater in approximate position 37°56.507'S, 144°59.532'E (WGS84) is re-established.

**Charts & Publications**

**Affected:** AUS143, AUS155, AU5SAN01, AU438144.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

David Ritman  
A/ Manager Reginal Operations  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).