

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**06 October 2025**  
**Australia – Victoria**

**No. 485(T)-2025**

**Local Port of Port Phillip**

**Point Cook**  
**East Cardinal Beacon Temporarily Replaced with Buoy**

**Date:** **Immediate**

**Previous Notice:** 484(T)-25 is referred

**Details:** Mariners are advised that the East Cardinal Beacon 'Point Cook' with characteristics Q(3)W 10s7m3M, with charted position east of Point Cook Marine Sanctuary at approximate location: 37°55.584'S, 144°48.913'E (WGS84), has been temporarily replaced with a buoy of the same characteristics.

The old beacon has been removed. The new beacon as detailed in Notice 484(T)-25 has not yet been installed.

**Mariners are advised to navigate with caution in the vicinity of the buoy.**

## **Charts & Publications**

**Affected:** AUS143, AUS155, AU5MEL01, AU438144.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

David Ritman  
Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au)