

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 11 March 2021
Australia – Victoria

No. 063 – 2021

Local Port of Western Port

Watson Inlet
Watson Inlet Port Lateral Pile No. 2 Removed

Date: Immediate

Details: Mariners are advised that the unlit Port Lateral Mark pile No. 2, marking the south-eastern extent of the entrance to Watson Inlet, at approximate location 38°15.711'S, 145°15.601'E (WGS84) is now redundant and has been removed.

The existing lit Port Lateral Mark pile No. 4 at approximate location: 38°15.697'S, 145°15.682'E (WGS84) with characteristics Fl. R 3s marks the entrance to Watson inlet.

Mariners are advised to navigate with caution within the vicinity of Watson Inlet.

Charts & Publications

Affected: AUS 150, 151

Further Notice: No Further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.