

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 04 January 2021 Australia – Victoria

No. 002 - 2021

**Local Port of Port Phillip** 

Mordialloc

**Entrance of Mordialloc Creek – Reduced Depth** 

Date: Immediate

Previous Notice: 373-20 is referred and cancelled

**Details:** Mariners are advised of a reduced depth at the entrance to Mordialloc Creek at

approximate location 38°00.665'S, 144°05.070'E (WGS84).

Scheduled maintenance dredging works have been delayed by unsuitable weather

and have not yet been undertaken.

Apologies for any inconvenience caused by the previous miscommunication in

Notice 373-20, depth will be restored as soon as practicable.

The most recent hydrographic survey showing the reduced depth is attached

below.

Mariners are advised to navigate with caution within the vicinity of Mordialloc

Creek.

**Charts & Publications** 

Affected: AUS 143

**Further Notice:** A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <a href="mailto:noticetomariners@parks.vic.gov.au">noticetomariners@parks.vic.gov.au</a>. To view Notices, visit <a href="https://www.parks.vic.gov.au">www.parks.vic.gov.au</a>.





## MORDIALLOC CREEK -- MONITORING SURVEY 29 December 2020

Parks Victoria does not warrant that the information provided is accurate and up to date.

All boat operators are advised to navigate with caution, as conditions can change quickly, sand can accumulate across the entrance and cause shallowing through the channel.

The information provided is intended as a guide only and does not replace the judgement of the operator of the vessel. Boat operators are advised to check weather and tidal conditions prior to accessing the entrance. Depth shown is to Chart Datum.



