

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**16 January 2024**  
**Australia – Victoria**

**No. 020(T) - 2024**

**Local Port of Port Phillip**

**Sandringham**  
**Sandringham Yacht Club Special Mark Buoy 'SYC1' Missing**

**Date:** **Immediate**

**Details:** Mariners are advised that the Sandringham Yacht Club lit Special Mark Buoy SYC1, with characteristics Fl(4).Y.10s at approximate location (WGS84) 37° 57.810'S, 144° 58.876'E is missing.

The buoy and light will be reinstated as soon as practicable.

**Mariners are advised to navigate with caution within the vicinity of the missing buoy.**

## **Charts & Publications**

**Affected:** AUS143, AUS155, AU5SAN01, AU438144.

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact Sandringham Yacht Club on (03) 9599 0999.**

David Ritman

Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).