

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

19 January 2026
Australia – Victoria

No. 040(T) - 2026

Local Port of Port Phillip

Portsea
Collins Bay Special Mark Buoy Missing

Date: **Immediate**

Details: Mariners are advised that the lit Special Mark buoy with characteristics FL (Y) 2.5s, marking a wave monitoring buoy in the vicinity of Collins Bay, Portsea at the following approximate location (WGS84): 38° 019.222' S, 144° 43.914' E is missing.

The 'Spotter' wave monitoring buoy that it was marking remains at the charted location and is lit with characteristics FL(Y)2.5s but has limited visibility.

Mariners are advised to navigate with caution within the vicinity of the wave monitoring buoys.

Charts & Publications

Affected: AUS143, AUS144, AU5RIP01, AU439144.

Further Notice: A further Notice will be issued.

If you require any further information, please contact DEECA on 136 186.

David Ritman
Planning and Coordination Manager
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.