

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 25 February 2022 Australia – Victoria

No. 072 - 2022

**Local Port of Port Phillip** 

**Portsea** 

Portsea Hole Special Mark Buoy Light Reinstated

Date: Immediate

**Previous Notice:** 055(T)-22 is referred and cancelled

**Details:** Mariners are advised that the special mark buoy light, with characteristics

Fl.Y.5s, marking the northern boundary of Portsea Hole, within Port Phillip

Heads Marine National Park, at approximate location (WGS84)

38°18.570'S, 144°42. 680'E has been reinstated.

Mariners are advised to navigate with caution within the vicinity of the

buoy.

**Charts & Publications** 

**Affected:** AUS 144, 158

**Further Notice:** No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <a href="mailto:noticetomariners@parks.vic.gov.au">noticetomariners@parks.vic.gov.au</a>. To view Notices, visit <a href="mailto:www.parks.vic.gov.au">www.parks.vic.gov.au</a>.

