

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 14 February 2023
Australia – Victoria

No. 079(T) - 2023

Local Port of Port Phillip

Werribee South
Wyndham Harbour Breakwater Special Mark Buoy Missing

Date: Immediate

Details: Mariners are advised that the lit special mark buoy marking the end of the breakwater at Wyndham Harbour, with characteristics Fl.Y.6s at approximate location 37° 58.076'S, 144° 42.611'E (WGS84) is missing.

The buoy and light have been recovered and will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the buoys location.

Charts & Publications

Affected: AUS 143, 155

Further Notice: A further Notice will be issued.

If you require any further information, please contact Wyndham Harbour on (03) 9233 8530

Peter Kemp

A/Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.