

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

11 February 2025
Victoria - Australia

No. 082(T) - 2025

Local Port of Port Phillip

Portsea
Collins Bay - 5 Knot Special Mark Buoy - Missing

Date: **Immediate**

Details: Mariners are advised that the unlit 5-knot special mark buoy at approximate location: 38°19.242'S, 144°43.987'E (WGS84), is missing.

The buoy will be re-established as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Collins Bay, Portsea.

Charts & Publications

Affected: AUS 143, AU5RIP01, AU439144

Further Notice: A further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963.

David Ritman
Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.