

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 24 March 2020
Australia – Victoria

No. 114 - 2020

Local Port of Port Phillip

Williamstown

Williamstown Mooring Field – Lit Isolated Danger Buoy Reinstated

Date: **Immediate**

Previous Notices: 068(T) – 2020 is referred and cancelled

Details: Mariners are advised that the isolated danger buoy lit with characteristics Fl(2)W10s, in the eastern portion of the Williamstown Mooring Field at approximate location 37°51.413'S, 144°54.229'E (WGS84) has been reinstated.

Mariners are advised to navigate with caution within the vicinity of the Williamstown Mooring Field.

Charts & Publications

Affected: AUS 143, 154, 155

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.