

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 28 April 2020
Australia – Victoria

No. 141 – 2020

Local Port of Port Phillip

Sandringham
Sandringham Harbour – Temporary Starboard Lateral Buoy Light Operational

Date: **Immediate**

Previous Notice: 115(T) – 2020 is referred and cancelled.

Details: Mariners are advised that the temporary Starboard Lateral Buoy light with characteristics Fl(2)G.5s, situated 30m from the end of Sandringham Breakwater at approximate location 37°56.507'S, 144°59.532'E (WGS84) is now operational.

Mariners are advised to navigate with caution within the vicinity of Sandringham Harbour.

Charts & Publications

Affected: AUS 143, 155

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

Victor Teoh

Senior Manager Local Ports and Waterways
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.