

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**18 March 2026**  
**Australia – Victoria**

**No. 162-2026**

**Local Port of Port Phillip**

**Point Cook**  
**East Cardinal Beacon Permanently Replaced with Buoy**

**Date:** **Immediate**

**Previous Notice:** 484(T)-25 is referred and cancelled,  
485(T)-25 is referred and cancelled.

**Details:** Mariners are advised that a permanent East Cardinal buoy 'Point Cook' with characteristics Q(3)W 10s, has been established at approximate location (WGS84): 37°55.646'S, 144°48.994'E (WGS84).

The buoy is shown in image 1 below and permanently replaces a beacon and a temporary buoy, as outlined in notices 484(T)-25 and 485(T)-25.

**Mariners are advised to navigate with caution in the vicinity of the buoy.**

## **Charts & Publications**

**Affected:** AUS143, AUS155, AU5MEL01, AU438144.

**Further Notice:** No further Notice will be issued.

**If you require any further information, please contact Parks Victoria on 13 1963.**

Scott Lever  
A/Planning and Coordination Manager  
Maritime and Waterways Operations

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au)

Image 1. Point Cook East Cardinal Buoy

