

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 2 June 2020
Australia – Victoria

No. 175(T) – 2020

Local Port of Port Phillip

Elwood to Sorrento

Installation of new & upgrade or removal of existing aids to navigation.

Date: 3 June to 10 July 2020, conditions permitting.

Details: Mariners are advised of the installation of new and the removal of existing aids to navigation in the near shore areas between Elwood to Sorrento, as detailed in the following table.

Works will be carried out using a pile-driving barge, support vessels and may include diving operations. On-water plant and machinery will be lit to IALA standards from sunset to sunrise. When divers are operating, a white and blue flag (Alpha) will be displayed in accordance with international standards.

Approximate locations (WGS84) of the new aids to navigation to be **either installed, removed and/or replaced** are:

<i>Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Function</i>		<i>Light Present</i>
Elwood	37°53.520'S	145°58.967'E	Special Mark	Remove pile	Unlit
Elwood	37°53.501'S	145°58.949'E	Special Mark	Install New Pile	Unlit
Aspendale	38°0.871'S	145°05.238'E	Special Mark	Remove Pile	Unlit
Aspendale	38°0.804'S	145°5.173'E	Special Mark	Install New Pile	Unlit
Aspendale	38°0.925'S	145°5.294'E	Special Mark	Install New Pile	Unlit
Aspendale	38°0.985'S	145°5.352'E	Special Mark	Install New Pile	Unlit
Aspendale	38°1.323'S	145°5.631'E	Special Mark	Install New Pile	Unlit

<i>Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Function</i>		<i>Light Present</i>
Chelsea	38 03.132'S	145 06.601	Special Mark	Remove Pile	Unlit
Chelsea	38°3.107'S	145°56.589'E	Special Mark	Install New Pile	Unlit
Bonbeach	38 03.625'S	145 06.796'E	Special Mark	Remove & reinstall new pile	Unlit
Carrum	38°04.767'S	145°07.141'E	Special Mark	Remove Pile	Unlit
Carrum	38°04.823'S	145°07.154'E	Special Mark	Install New Pile	Unlit
Carrum	38°04.478'S	145°07.065'E	Lateral Port	Remove & reinstall new pile	Lit – Characteristics – QR
Carrum	38°04.452'S	145°07.061'E	Lateral Starboard	Remove & reinstall new pile	Lit – Characteristics – QG
Carrum	38°04.297'S	145°07.010'E	Special Mark	Remove & reinstall new pile	Unlit
Rye	38°22.082'S	144°49.233'E	Lateral Port	Remove buoy & install new pile	Unlit
Rye	38°22.096'S	144°49.308'E	Lateral Port	Remove buoy & install new pile	Unlit
Sorrento	38°19.479'S	144°44.534'E	Lateral Starboard	Remove buoy & install new pile	Lit – Characteristics – Fl.G.5s

Mariners are advised to navigate with extreme caution within the vicinity of the works.

Charts & Publications

Affected: AUS 143, 150, 155 & 158.

Further Notice: No Further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

Graeme Davis

District Manager Port Phillip Western Port
Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.