

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 22 June 2021 Australia – Victoria

No. 199(T) - 2021

Local Port of Port Phillip

Southern Port Phillip Pinnace Channel Aquaculture Fisheries Reserve – Updated Location for Missing Boundary Marker Buoy

Date: Immediate

Previous Notice: 169(T)-21 is referred

Details: Mariners are advised that the yellow special mark navigation buoy, lit with characteristics FL(4)Y.12s, marking north western boundary of the Pinnace Channel Aquaculture Fisheries Reserve northern zone, at approximate location 38°14.257'S, 144°48.864'E (WGS84), is missing.

The buoy and light will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of Pinnace Channel Aquaculture Fisheries Reserve.

Charts & Publications Affected: AUS 143 & 157

Further Notice: A further Notice will be issued.

If you require any further information please contact the Victorian Fisheries Authority on 136 186.

David Ritman

A/ Senior Manager Local Ports and Waterways Marine and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <u>noticetomariners@parks.vic.gov.au</u>. To view Notices, visit <u>www.parks.vic.gov.au</u>.

