

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 26 August 2022
Australia – Victoria

No. 285 – 2022

Local Port of Port Phillip

Queenscliff
Boat Ramp Lateral Mark Buoys Installed

Date: **Immediate**

Details: Mariners are advised that two lit lateral mark buoys have been installed in the vicinity of Queenscliff boat ramp, as outlined in the table below

Latitude	Longitude	Function	Light Characteristics
38° 15.767'S	144° 39.871'E	Port Lateral buoy	Fl.R.2s
38° 15.754'S	144° 39.835'E	Starboard Lateral buoy	Fl.G.2s

Shallow water exists outside of this channel, particularly towards the bank on the eastern side of the facility adjacent to the bridge.

Mariners are advised to keep within the channel and navigate with caution within the vicinity of Queenscliff Boat Ramp.

Charts & Publications

Affected: AUS 143, 144, 158

Further Notice: No further Notice will be issued.

If you require any further information, please contact the Borough of Queenscliffe on (03) 5258 1377.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.