

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 29 August 2022
Australia – Victoria

No. 288 – 2022

Local Port of Port Phillip

Sandringham
Sandringham Harbour – Starboard Lateral Buoy Reinstated

Date: **Immediate**

Previous Notices: 274(T) – 2022 is referred and cancelled.

Details: Mariners are advised that the Lit Starboard Lateral Buoy with characteristics FI(2)G.5s, situated 30m from the end of Sandringham Breakwater at approximate location 37°56.507'S, 144°59.532'E (WGS84) has been reinstated.

Charts & Publications

Affected: AUS 143, 155

Further Notice: No further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963.

David Ritman

Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.