

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

Melbourne, 27 September 2022
Australia – Victoria

No. 328(T)-2022

Local Port of Port Phillip

Portsea
Collins Bay East 5 knot Special Marker Buoy – Missing

Date: **Immediate**

Details: Mariners are advised that the Collins Bay East unlit 5 knot Special Marker buoy, charted at approximate location: 38° 19.241'S, 144° 43.987'E (WGS84), is missing.

The buoy will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the missing buoy

Charts & Publications

Affected: AUS 144, 158

Further Notice: A further Notice will be issued.

If you require any further information please contact Parks Victoria on 13 1963

Peter Kemp

A/Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au.