

# Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

**28 July 2025**  
**Australia – Victoria**

**No. 386(T) - 2025**

**Local Port of Port Phillip**

**Portsea**  
**Special Mark Buoy Missing**

**Date:** **Immediate**

**Previous Notice:** 333(T)-25 is referred  
385-25 is referred

**Details:** Mariners are advised that the lit Special Mark buoy with characteristics FL (Y) 2.5s, marking a wave monitoring buoy in the vicinity of Portsea Pier, Weeroona Bay at the following location (WGS84): 38°18.948' S, 144°42.742' E is missing.

The 'Spotter' wave monitoring buoy that it was marking remains at the charted location and is lit with characteristics FL(Y)2.5s but has limited visibility.

Notice 384-25 notifies that the buoy was reinstated, but it has since been damaged and is again missing.

**Mariners are advised to navigate with caution within the vicinity of the wave monitoring buoys.**

**Charts & Publications**

**Affected:** AUS143, AUS155, AUS157, AU5MEL01, AU5RIP01

**Further Notice:** A further Notice will be issued.

**If you require any further information, please contact DEECA on 136 186.**

David Ritman

Manager Regional Planning  
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to [noticetomariners@parks.vic.gov.au](mailto:noticetomariners@parks.vic.gov.au). To view Notices, visit [www.parks.vic.gov.au](http://www.parks.vic.gov.au).