

## **Victorian Notice to Mariners**

The following Notice to Mariners is published for general information.

Melbourne, 21 December 2021 Australia – Victoria

No. 411 - 2021

**Local Port of Port Phillip** 

Sorrento

**Sorrento Pier Western Lower Landing Fenders Repaired** 

Date: Immediate

**Previous Notice:** 344(T)-20 is referred and cancelled

**Details:** Mariners are advised that the berthing fenders on the Sorrento Pier western

low landing, at approximate location (WGS84) 38°20.132'S, 144°44.741'E have been repaired. Mariners should check weather, tides and condition of fenders above and below the waterline for suitability of berthing their vessel

on any structure.

Mariners are advised to navigate with caution within the vicinity of

**Sorrento Pier** 

**Charts & Publications** 

**Affected:** AUS 143, 150, 788

**Further Notice:** No further Notice will be issued.

If you require any further information, please contact Parks Victoria on 13 1963

David Ritman

Manager Regional Planning Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to <a href="mailto:noticetomariners@parks.vic.gov.au">noticetomariners@parks.vic.gov.au</a>. To view Notices, visit <a href="mailto:www.parks.vic.gov.au">www.parks.vic.gov.au</a>.

