

Victorian Notice to Mariners

The following Notice to Mariners is published for general information.

07 November 2025
Victoria - Australia

No. 541(T) – 2025

Local Port of Port Phillip

Black Rock
Wave Monitoring Special Mark Buoy Damaged

Date: **Immediate**

Previous Notice: 333(T)-25 is referred

Details: Mariners are advised that the Special Mark buoy with characteristics Fl(Y)2.5s, marking a wave monitoring buoy off Black Rock at approximate location (WGS84): 37°58.719'S, 144°59.730'E has been damaged. The wave monitoring buoy and special mark buoy may be unlit and have limited visibility.

The Special Mark and wave monitoring buoy arrangement will be reinstated as soon as practicable.

Mariners are advised to navigate with caution within the vicinity of the buoys.

Charts & Publications

Affected: AUS143, AUS155, AU438144.


Further Notice: A further Notice will be issued.

If you require any further information, please contact DEECA on 136 186.

David Ritman
Manager Regional Planning
Southern and Maritime Region

If you wish to receive Parks Victoria issued Notice to Mariners, please email your details to noticetomariners@parks.vic.gov.au. To view Notices, visit www.parks.vic.gov.au

Figure 1. Wave monitoring buoy arrangement



BOUY ARRANGEMENT